

Fixing Seats

◀ Adhesive Type/Screw Type


Adhesive Type

Code	Type	Material	Flammability Rating	Operating Temperature
ZIL17	Adhesive Type	Nylon 66	UL94V-2	-40°C~+85°C


Instructions:

- When using, tear off the sealing paper from the tape on the bottom surface, then stick the fixing seat on the iron plate, and then use the cable tie to pass through the hole to fasten.


Hole Width: 3.2




Hole Width: 4.5




Hole Width: 5.4



Hole Width: 5.4A



Method of Sales	Quantity per Bag
Bag	500PCS



Part Number		Color	Method of Sales	Length L	Width W	Height H	Screw Hole Diameter
Code	Hole Width						
ZIL17	3.2	W (White)	Bag (500 Pcs/Bag)	12.5	12.5	3.2	Without Holes
	4.5			19	19	3.9	Ø3
	5.4			25.8	25.8	6.1	Ø3.2
	5.4A			28	28	5.3	Ø5.5



Part Number		Color
Code	Hole Width	
ZIL17	3.2	W (White)
	4.5	

ZIL17—3.2—W


Screw Type

Code	Type	Material	Flammability Rating	Operating Temperature
ZIL18	Screw Type	Nylon 66	UL94V-2	-40°C~+85°C


Instructions:

- Use the fixing base to fix it with screws and wrap the cables with cable ties. The saddle-shaped design makes it easy to fix the cable.


Specification: 5




Specification: 4/5A/9/9A




Specification: 5.4



Specification: 8.5/9.3



Method of Sales	Quantity per Bag
Bag	100PCS



Part Number		Color	Method of Sales	Hole Width	Length L	Width W	Height H	Diameter B
Code	Specification							
ZIL18	4	W (White)	Bag (100 Pcs/Bag)	4	12.8	7	5.9	3.3
	5			5	19	9.5	5	3.4
	5A			5	15	10	7	3
	5.4			5.4	19.1		6.2	4.2
	8.5			8.5	13.8	17.5	5.3	
	9	B (Black)		9	23	16	9	6
	9A							5
	9.3			9.3	30	14.7	9.3	5.2



Part Number		Color
Code	Specification	
ZIL18	5	W (White)
	5A	

ZIL18—5—W