
## X-Axis, Standard >


**Push Screw** 

## **Simplified Adjustments**



Part Number		7		Stage Surface		Load Capacity(N)		The amount of movement for one turn of the knob	Weight	
Code	No.	Ζ		(mm)	(mm)	Horizontal	Vertical	(mm)	(g)	
HHJ01	20	18	28	38	20×20	ERT ±5	9.8	2	0.5	38
	25		20		25×25					55
	40	19.5 30 40 19.5 40 60	40	40×40	±7.5	14.7	0	0.5	104	
	60		60×60	±1.5	14.7	0		193		

1 Travel Distance Per Handle Rotation: 0.5 mm.



Please order as shown





